



Thread Ring Reconfiguration



Products Affected	
FS1096	FS19593
FS19521	FS19798
FS19538	FS19799
FS19590	FS19946
FS19591	FS20040

As part of our ongoing efforts to improve our products and processes, Fleetguard will be modifying the internal thread ring and bottom end cap on a few spin-on filter families.

Customers who are affected by this change will be able to continue to use their current plastic and metal bowls with the new filters.

Current Design



New Design



If you have any questions, please contact your local sales representative or call Customer Assistance at **1-800-22-FILTER**

