

## E. PRODUCT GUIDE

<b>LF16212</b>	Ford E1EE-6714AA, GMC 710319 Mexico Only  Overall Height: 4.88 (124) End 1 OD: 2.91 ( 74) End 1 ID: ¾ in. – 16 UNF -2B Antidrainback Valve Yes
<b>LF16213</b>	Chrysler 3241398, GMC 6439929 Mexico Only  Overall Height: 3.35 ( 85) End 1 OD: 2.91 ( 74) End 1 ID: M18 X 1.5 – 6H
<b>LF16214</b>	Ford F1AZ6731A Mexico Only  Overall Height: 3.86 (98) End 1 OD: 3.66 (93) End 1 ID: M22 X 1.5 – 6 H Antidrainback Valve Yes
<b>LF16215</b>	CHRYSLER 5281090 Mexico only  Overall Height: 3.86 (98) End 1 OD: 3.66 (93) End 1 ID: 13/16 in. – 16 UNF – 2B Antidrainback Valve Yes
<b>LF16216</b>	GMC 5578052 Mexico only Overall Height: 4.09 (104) End 1 OD: 3.66 ( 93) End 1 ID: 13/16 in.– 16 UNF – 2B
<b>LF16217</b>	GMC 12555891 Mexico only
<b>LF16218</b>	GMC 25014377 Mexico only
<b>LF16219</b>	GMC 25010251 Mexico only
<b>LF16220</b>	GMC 25010792 Mexico only
<b>LF16222</b>	NISSAN 1520855Y00 Mexico only

<b>LF42502</b>	AC PF39, AC PF44, AC PF46, GMC 25014377   Product is not available in all regions of the world. Is User Friendly Version of: LF3945 LF796  Gasket OD: 2.81 (71) Overall Height: 3.37 (86) Seam OD: 3.24 (82) Standpipe: NO Thread Size: 13/16-16 UNS
----------------	--

<b>LF42504</b>	FORD D0RY6731A, TOYOTA 1560133020   Product is not available in all regions of the world. Is User Friendly Version of: LF655  Gasket OD: 2.81 (71) Overall Height: 4.56 (116) Seam OD: 3.24 (82) Standpipe: NO Thread Size: 3/4-16 UNF
----------------	---

<b>LT20270</b>	Literature ES EG Sticker, to build MK12550
----------------	---

<b>LT20276</b>	Literature, ES Filter Sticker, to build MK12550
----------------	--

### Maintenance Kits

<b>MK3CE</b>	CUMMINS LF750B, LF516, FF105, WF2071
<b>MK31M</b>	MACK LF667(2), FF172, FF171, WF2015
<b>MK33M</b>	MACK LF667(3), FF172, FF222, WF2022
<b>MK198</b>	CUMMINS LF750B, LF670, FF105, WF2071, 164159S
<b>MK1410</b>	CUMMINS LF777(2), LF670(4), FF202(2), WF2071(4)
<b>MK1451</b>	CUMMINS LF777, LF670, FS1212, WF2071
<b>MK1462</b>	CATERPILLAR LF691, FF211
<b>MK1465</b>	CUMMINS LF777, LF670, FF105, WF2071
<b>MK1466</b>	INTERNATIONAL TRUCKS LF3316(2), FF5020, FF5019
<b>MK1468</b>	CUMMINS LF777, LF670, FF105
<b>MK1483</b>	CUMMINS LF777, LF670, FF104, WF2071

<b>MK1519</b>	INTERNATIONAL TRUCKS LF3316(2), FF5020, FF5019, WF2051
<b>MK1530</b>	CUMMINS LF777, LF670, FS1212
<b>MK1538</b>	CUMMINS LF777, LF670(2), FS1212(2), WF2071
<b>MK1547</b>	CATERPILLAR LF3342(2), FF185
<b>MK1549</b>	DETROIT DIESEL LF670, FF5207, FF5206
<b>MK1599</b>	INTERNATIONAL TRUCKS LF3344, FF5035, FF194
<b>MK11002</b>	INTERNATIONAL TRUCKS LF690(2), FF196, FF5019
<b>MK11012</b>	THERMO-KING LF3361, FF204
<b>MK11021</b>	INTERNATIONAL TRUCKS LF3316(2), FF5020, FF5019, WF2071
<b>MK11029</b>	INTERNATIONAL TRUCKS LF3420(2), FF5020, FF5019
<b>MK11033</b>	CARRIER LF778, LF699, FF200, FF185
<b>MK11053</b>	CUMMINS LF3000, FS1212, WF2071
<b>MK11057</b>	MACK CS41000, LF667(2), FF172, FF222, WF2022
<b>MK11059</b>	CATERPILLAR LF691, FF211, WF2071
<b>MK11060</b>	CATERPILLAR LF691, FF211, FF105
<b>MK11065</b>	FORD LF3443(2), FF5095(2)
<b>MK11066</b>	CUMMINS LF3000, FF105, WF2071
<b>MK11115</b>	CATERPILLAR LF691, FF211, FS1212, WF2071
<b>MK11116</b>	MACK LF667(2), FF172, FF222
<b>MK11128</b>	CUMMINS LF3000, FF105
<b>MK11146</b>	FORD LF3443(2), FF5095(2), FS1234, WF2070
<b>MK11148</b>	CARRIER LF699, FF200, FF185
<b>MK11215</b>	DETROIT DIESEL LF777, LF3333(2), FF5207, FF5206

<b>LF42500</b>	OPEL 2866477   Product is not available in all regions of the world. Is User Friendly Version of: LF3310  Gasket OD: 2.81 (71) Overall Height: 3.37 (86) Seam OD: 3.24 (82) Standpipe: NO Thread Size: 3/4-16 UNF
----------------	--

## E. PRODUCT GUIDE

<b>MK11217</b>	CUMMINS LF3000, FS1212, WF2077	<b>MK11443</b>	CATERPILLAR LF691A, FF211, FS1212	<b>MK11612</b>	FORD LF3443(2), FF5095(2), FS1247, WF2070
<b>MK11225</b>	CUMMINS LF3349, FF5052, FS1280	<b>MK11446</b>	CUMMINS LF777, LF670, FF105(2), WF2071	<b>MK11614</b>	CUMMINS LF3000, FF5052, FS1280, WF2070
<b>MK11267</b>	INTERNATIONAL TRUCKS LF3455(2), FF5020, FF5019	<b>MK11447</b>	GMC LF3342, FF5033, AF400, LF692	<b>MK11620</b>	DETROIT DIESEL LF3620(2), FF5206, FS1212, WF2071
<b>MK11273</b>	FORD LF3443(2), FF5095(2), FS1234, WF2071	<b>MK11467</b>	CUMMINS LF3000, FS1212, WF2072	<b>MK11623</b>	DETROIT DIESEL LF3620(2), FF5206, WF2071
<b>MK11277</b>	INTERNATIONAL TRUCKS LF3420(2), FF5020, FF5019, WF2071	<b>MK11498</b>	CUMMINS LF3000, FS1251, WF2071	<b>MK11632</b>	CUMMINS LF3363(3), FF202(2)
<b>MK11356</b>	CUMMINS LF3000, FS1206, WF2071	<b>MK11499</b>	CUMMINS LF3349, FF42000, FS1240, HF6056, HF6243	<b>MK11651</b>	INTERNATIONAL TRUCKS LF3883, FF5078, WF2106, CC2525
<b>MK11361</b>	CUMMINS LF3000, FS1212	<b>MK11511</b>	CATERPILLAR LF667, FF185, FF105	<b>MK11654</b>	CUMMINS LF3000, FF105, WF2053
<b>MK11362</b>	MACK CS41000, LF667(2), FF172, FF222	<b>MK11513</b>	GMC LF653, FF5033, AF380	<b>MK11661</b>	DETROIT DIESEL LF3620(2), FF5206, FS1212
<b>MK11368</b>	CATERPILLAR LF691A, FF211, FS1212, WF2071	<b>MK11517</b>	CATERPILLAR LF691A, FF211, FF105, WF2071	<b>MK11663</b>	INTERNATIONAL TRUCKS LF3883, FF5078
<b>MK11371</b>	CATERPILLAR LF691, FF211, FS1212	<b>MK11519</b>	CUMMINS LF3349, FS1251	<b>MK11665</b>	CATERPILLAR LF3566, FF211, WF2071
<b>MK11372</b>	CATERPILLAR LF691A, FF211, WF2071	<b>MK11556</b>	CUMMINS LF3000, FS1212, WF2051	<b>MK11666</b>	DETROIT DIESEL LF3620(2), FF5207, FF5206, WF2071
<b>MK11375</b>	DETROIT DIESEL LF3333(2), LF777, FF5206	<b>MK11557</b>	FORD LF697, FF5033, HF6056, AF4967	<b>MK11669</b>	CATERPILLAR LF667, FF185, WF2071
<b>MK11387</b>	INTERNATIONAL TRUCKS LF3420(2), FF5078	<b>MK11562</b>	DETROIT DIESEL LF3620(2), FF5207, FF5206	<b>MK11699</b>	CATERPILLAR LF691A, FF211, DCA60L
<b>MK11389</b>	INTERNATIONAL TRUCKS LF3455(2), FF5020, FF5019, WF2071	<b>MK11577</b>	VOLVO LF777, LF3321, FF42000(2)	<b>MK11726</b>	INTERNATIONAL TRUCKS LF3883, FF5078, WF2106
<b>MK11394</b>	FORD LF3443(2), FF5095(2), WF2071	<b>MK11582</b>	INTERNATIONAL TRUCKS LF3420(2), FF5078, FS1205, WF2071	<b>MK11736</b>	IHC LF3883, FF5078, WF2071
<b>MK11397</b>	CATERPILLAR LF691A, FF211, FF105	<b>MK11584</b>	THERMO-KING LF3536, FF204	<b>MK11743</b>	ISUZU LF3563, LF3328, FF5108
<b>MK11402</b>	DETROIT DIESEL LF777, LF3333(2), FF5206, FS19513, WF2071	<b>MK11585</b>	CUMMINS LF3000, FF5052	<b>MK11772</b>	CATERPILLAR LF691A(2), HF6098(4), HF6097
<b>MK11412</b>	MACK CS41000, LF667(2), FF172, FF222, WF2015	<b>MK11593</b>	DETROIT DIESEL LF3620(2), FF5206	<b>MK11776</b>	CUMMINS LF777(2), LF670(3), LF509N(2)
<b>MK11424</b>	CUMMINS LF3000, FS1242	<b>MK11600</b>	DETROIT DIESEL LF3620(2), FF5206, FS19513, WF2071	<b>MK11778</b>	CUMMINS LF777(2), LF670(4), FF202(2)
<b>MK11429</b>	MITSUBISHI LF3447, LF3432	<b>MK11601</b>	CUMMINS LF3000, FF213	<b>MK11779</b>	CUMMINS LF777(2), LF670(4)
<b>MK11437</b>	CATERPILLAR LF691A, FF211, FS19513, WF2071	<b>MK11606</b>	DETROIT DIESEL LF3620(2), FF5206, FS19513	<b>MK11791</b>	ISUZU LF3622, FF5114
<b>MK11442</b>	CATERPILLAR LF691A, FF211, FS1206	<b>MK11608</b>	CUMMINS LF3000, FF5052, FS1247, LF3342	<b>MK11800</b>	DETROIT DIESEL LF3620(2), WF2071, FF5369W

## E. PRODUCT GUIDE

<b>MK11802</b>	CATERPILLAR LF691A, FF5264	<b>MK12008</b>	CUMMINS LF3000, FF5369W	<b>MK12127</b>	CATERPILLAR LF3566(2), FF5319(2), WF2052, 3838230S
<b>MK11807</b>	CUMMINS LF3000, FS1000	<b>MK12014</b>	THERMO-KING LF3746, FF5275, FF5276, AH1189	<b>MK12131</b>	DETROIT DIESEL LF3620(2), FF5206, FS1206, WF2071
<b>MK11808</b>	CUMMINS LF3000, FS1000, DCA60L	<b>MK12017</b>	CATERPILLAR LF691A(2), FF211(2)	<b>MK12133</b>	VOLVO LF3654, LF3321(2), FF5272, WF2108
<b>MK11811</b>	CUMMINS LF3000, FS1000, WF2071	<b>MK12019</b>	DETROIT DIESEL LF3620(2), FF5207, FF5206, DCA60L	<b>MK12134</b>	CATERPILLAR LF691, FF5264, WF2071
<b>MK11813</b>	CUMMINS LF3000, FS1000, WF2072	<b>MK12020</b>	CATERPILLAR LF691, FF213, FF211, WF2073	<b>MK12136</b>	DETROIT DIESEL LF9620(2), FF5206, FS19513
<b>MK11814</b>	CUMMINS LF3000, FS1000, WF2073	<b>MK12021</b>	CATERPILLAR LF691A(2), LF667, HF6097(2)	<b>MK12138</b>	MACK CS41000, LF667(2), WF2015
<b>MK11837</b>	DETROIT DIESEL LF3333SC, FF235, FF5021	<b>MK12024</b>	DETROIT DIESEL LF3671(2), FF5207, FF5206	<b>MK12145</b>	CUMMINS LF3000, FF5369W, WF2071
<b>MK11841</b>	CUMMINS LF3000, FF5052, WF2072	<b>MK12025</b>	CUMMINS LF3000, FS1001, WF2071	<b>MK12146</b>	VOLVO LF3654, LF3675(2), FF5272, WF2108
<b>MK11842</b>	INTERNATIONAL TRUCKS LF3883, FF5078, WF2072	<b>MK12036</b>	CUMMINS LF777(2), LF670(3), FF202	<b>MK12150</b>	INTERNATIONAL TRUCKS LF3883, FF5269
<b>MK11843</b>	INTERNATIONAL TRUCKS LF3630, FS1298, WF2071	<b>MK12039</b>	CATERPILLAR LF691A, FF5369W, WF2071	<b>MK12151</b>	INTERNATIONAL TRUCKS LF3883, FF5052
<b>MK11844</b>	CUMMINS LF3349, FF5052	<b>MK12042</b>	CATERPILLAR LF691A(2), FF185, FF211, LF667	<b>MK12154</b>	THERMO-KING LF3641, LF3536, FF204
<b>MK11861</b>	FORD LF3681, FF5244	<b>MK12043</b>	TOYOTA LF3599, AF25308	<b>MK12159</b>	CATERPILLAR LF3379, FF185, FF105, WF2071
<b>MK11868</b>	GMC LF782, FF5026	<b>MK12048</b>	CUMMINS LF3000, FS1001	<b>MK12160</b>	MACK CS41000, LF667(2), FF222, FS1219, WF2015
<b>MK11874</b>	CUMMINS LF3349(2), FS1253, AF25090	<b>MK12049</b>	CATERPILLAR LF691A, FF211	<b>MK12174</b>	MACK CS41000, LF667(2), FF222, FF172, WF2083, CC2602B
<b>MK11884</b>	TOYOTA LF3311, LF3400, AF437K	<b>MK12050</b>	DETROIT DIESEL LF3620(2), FF5369W, WF2077	<b>MK12175</b>	CUMMINS WF2121, CC2602B, CC2840, CC2607B
<b>MK11890</b>	CATERPILLAR LF691A, FF211, FS1000, WF2071	<b>MK12054</b>	DETROIT DIESEL LF9620(2), FF5207, FF5206	<b>MK12176</b>	CATERPILLAR LF3342(2), FF5245
<b>MK11916</b>	INTERNATIONAL TRUCKS LF3883, FF5078, HF6057	<b>MK12059</b>	MERCEDES-BENZ LF3607(2)	<b>MK12180</b>	INTERNATIONAL TRUCKS LF3883, FF5269, WF2071
<b>MK11959</b>	CUMMINS FS1280, FF5052	<b>MK12060</b>	CUMMINS LF3000, FS1251	<b>MK12185</b>	INTERNATIONAL TRUCKS LF3455(2), FF5078, AF364, HF6056, HF6110, HF6162
<b>MK11967</b>	CATERPILLAR LF3566, FF211, FS1212	<b>MK12072</b>	CARRIER LF778, LF787, FF5301	<b>MK12201</b>	INTERNATIONAL TRUCKS LF3630, FS1298, WF2071, HF6056
<b>MK11971</b>	INTERNATIONAL TRUCKS LF3883, FF5269, WF2106	<b>MK12073</b>	THERMO-KING LF3746, FF5275, FF5276	<b>MK12221</b>	CATERPILLAR LF691A, LF777, FF5264
<b>MK11977</b>	GMC LF3679, FS1295	<b>MK12107</b>	CATERPILLAR LF667, FF5324, WF2052	<b>MK12223</b>	DETROIT DIESEL FF5369W, LF3620(2)
<b>MK11978</b>	FORD LF3630, FS1298	<b>MK12119</b>	CUMMINS LF3639, FS1000, WF2071	<b>MK12235</b>	DETROIT DIESEL FF5369W, LF3671(2)
<b>MK11996</b>	CUMMINS LF3000, FS1001, WF2073	<b>MK12120</b>	CATERPILLAR LF691, FF211, FS1000, WF2071		
<b>MK11997</b>	CUMMINS LF3639, FS1212, WF2071				
<b>MK12001</b>	VOLVO LF3654, LF3675(2), FF5272				

## E. PRODUCT GUIDE

MK12238	DETROIT DIESEL LF3620(2), FF5207	MK12351	CATERPILLAR LF667, FF5324	MK12402	MACK FF5381, FF5382, LF667(2), CS41000
MK12248	INTERNATIONAL TRUCKS LF3883, WF2071, FF5019	MK12352	CATERPILLAR LF667, FF5321	MK12404	CUMMINS LF9000, FS1000, WF2071
MK12252	CATERPILLAR LF691, FF5264	MK12353	CATERPILLAR LF691A, FF5319	MK12405	CUMMINS LF3342, LF3349, FS1251, FF5079, HF6510
MK12253	VOLVO FF5272, LF3321(2), LF3654	MK12354	GMC LF782, FF5033	MK12406	CATERPILLAR LF691A, FF5207, FF5264, WF2071
MK12257	CUMMINS LF9009, FS1000, WF2071	MK12357	CUMMINS LF3970, FS19579E	MK12411	CUMMINS LF3970, LF3342, HF6057, FS19579E
MK12258	CUMMINS LF750B, LF670, FS1001, WF2071	MK12358	DETROIT DIESEL LF3620(2), FS1029W	MK12418	CATERPILLAR LF667, FF5324, FF5052
MK12259	CUMMINS LF670, LF777, FS1001, WF2071	MK12364	DETROIT DIESEL LF3620(2), FF5369W, WF2071, CC2525	MK12421	NISSAN LF3434, AF4973K
MK12260	CATERPILLAR FF5319(2), LF691A(2)	MK12368	CATERPILLAR LF667, FF5321, FF5207	MK12425	ISUZU LF3379, FF5052, FF5321
MK12264	INTERNATIONAL TRUCKS FF5269, HF6057, LF3883	MK12369	TRANSICOLD LF3490, FF185	MK12430	CUMMINS LF3000, FF5369W, CC2602B
MK12265	CATERPILLAR FF185, FF5319, LF667, LF691A(2)	MK12370	CATERPILLAR LF667, FF5321, WF2071	MK12435	CUMMINS LF9001, FS1000, WF2072
MK12267	CATERPILLAR LF691A, FF211, FF213	MK12371	THERMO-KING LF3536, FF204, LF3361	MK12436	CATERPILLAR LF3379, FF5321
MK12269	CATERPILLAR LF667, FF5324, FS1001	MK12376	INTERNATIONAL TRUCKS LF3883, FS1281, FF5269	MK12437	GMC LF692, LF3342, FF5033, AF25259
MK12272	CUMMINS LF3363, FS1001, WF2071	MK12379	GMC LF692, LF3342, FF5033	MK12438	CATERPILLAR LF691A, FF5319, FS1001
MK12277	CUMMINS LF3363, FS1001(2), HF6110(2), HF6111(3), WF2073	MK12381	CATERPILLAR LF691A, FF5319, FF5207	MK12439	CUMMINS LF9000, FF5369W, WF2071
MK12310	CUMMINS LF9009, WF2072, FS1000	MK12382	DETROIT DIESEL LF3380, FF235, FF5021	MK12441	CUMMINS LF9009, FS1000, WF2073
MK12312	CUMMINS LF3000, FS1000, CC2602B, CC2525	MK12384	CUMMINS LF3000, FS1251, WF2072	MK12442	CATERPILLAR LF9691A(2), FF5319(2), WF2052
MK12313	CUMMINS LF9000, FS1000, CC2602B, CC2525	MK12389	CUMMINS LF3000, FS1022, WF2071	MK12443	KOMATSU LF3363(2), FS1000(2), LF777, WF2052
MK12320	CUMMINS LF9009, FS1212	MK12390	CUMMINS LF9009, FS1000, WF2077	MK12445	CATERPILLAR LF9691A(2), FF5319
MK12331	VOLVO LF3321, LF3654, FF5074(2)	MK12391	FORD AF25590, LF3681, FF5033	MK12449	CATERPILLAR HF6341(2), HF6342(2)
MK12339	MACK LF667(2), FF5381, FF5382	MK12392	CUMMINS LF9001, FS1011	MK12450	MACK LF3379, CS41000, FF5381, FF5382, WF2015
MK12343	CATERPILLAR LF691A, FS1212, FF5319, WF2071	MK12393	CUMMINS LF3000, FS1022	MK12452	CATERPILLAR LF9691A(2), FF5319, WF2052
MK12348	MACK FF5381, FF5382, LF667(2), WF2015, CS41000	MK12394	CUMMINS LF3000, FS1022, WF2074	MK12453	CATERPILLAR HF6344(4), HF6341
		MK12396	CATERPILLAR FF5035, LF667		
		MK12401	CUMMINS LF3000, FS1029W, CC2602B		

## E. PRODUCT GUIDE

<b>MK12457</b>	CATERPILLAR LF9691A, FF5319, WF2051	<b>MK12506</b>	HOLDEN AF1649, FF5030, LF3433	<b>MK12559</b>	CUMMINS LF9001, FS1007, WF2126
<b>MK12460</b>	CATERPILLAR LF9691, FS1000, FF5319, WF2072	<b>MK12507</b>	HOLDEN AF25372, FF5030, LF3528	<b>MK12560</b>	THERMO-KING LF694, FF204, FS1225
<b>MK12466</b>	CATERPILLAR LF9691A, FF5319	<b>MK12508</b>	HOLDEN AF1649, FF149, LF3336	<b>MK12561</b>	THERMO-KING LF787, FF185, FF200
<b>MK12471</b>	CATERPILLAR LF691A, FF5319, FS1000, WF2071	<b>MK12509</b>	HOLDEN AF4975, FF5180, LF3462	<b>MK12563</b>	CUMMINS FF42000, FS1240, HF6243, HF6710, HF7996, LF3349
<b>MK12472</b>	CATERPILLAR LF3566, FF5319, FS1000, CC2525	<b>MK12512</b>	NISSAN AF1649, FF5114, LF690	<b>MK12566</b>	CUMMINS LF9009, FS1022
<b>MK12473</b>	MACK LF3379(2), CS41000, FF5381, FF5382	<b>MK12513</b>	NISSAN AF4615, FF5180, LF3434	<b>MK12568</b>	DETROIT DIESEL LF3620(2), FS1029W, WF2073
<b>MK12476</b>	CUMMINS LF9001, FS1000, WF2071	<b>MK12514</b>	NISSAN FF5307, LF3659	<b>MK12582</b>	THERMO-KING LF694, LF695, FF185, FF204
<b>MK12478</b>	DETROIT DIESEL LF3671(2), FF5206	<b>MK12515</b>	NISSAN AF1778, FF5180, LF3434	<b>MK12588</b>	CATERPILLAR LF691A, FF5319, WF2077
<b>MK12479</b>	CUMMINS LF9000, FS1000, WF2122	<b>MK12516</b>	NISSAN AF1649, FF5180, LF3435	<b>MK12589</b>	CUMMINS LF9009, FS1000, WF2070
<b>MK12484</b>	CATERPILLAR LF667, FF5207, FF5321, LF3342	<b>MK12517</b>	NISSAN AF1778, FF146, LF3434	<b>MK12593</b>	CUMMINS LF9009, FS1029W, WF2072
<b>MK12486</b>	DETROIT DIESEL LF3620(2), FS1029W	<b>MK12518</b>	TOYOTA FF5159, LF3313	<b>MK12596</b>	CUMMINS LF9001, FS1040, WF2126
<b>MK12487</b>	CUMMINS LF9001, FS1000, CC2602B	<b>MK12519</b>	TOYOTA AF25295, FF5159, LF3313	<b>MK12599</b>	ISUZU LF551A, FF5108
<b>MK12488</b>	CUMMINS LF3000, FS1000, CC2602B	<b>MK12520</b>	TOYOTA AF4509, FF5114, LF3313	<b>MK12600</b>	KOMATSU AF1862M, AF1863M
<b>MK12489</b>	DETROIT DIESEL LF3620(2), FF5206, FF5207, CC2602B	<b>MK12521</b>	TOYOTA AF4509, FF5030, LF3313	<b>MK12601</b>	KOMATSU AF1935M, AF1934M
<b>MK12494</b>	INTERNATIONAL TRUCKS LF3883, FF5095	<b>MK12522</b>	TOYOTA FF5030, LF3399	<b>MK12622</b>	MACK LF667(2), CS41000, FF5369W
<b>MK12496</b>	CATERPILLAR LF691, FF5369W	<b>MK12525</b>	mitsubishi FF5160, LF3830	<b>MK12623</b>	MACK LF667(2), CS41000, FF5381, FF5382, FF222
<b>MK12498</b>	DETROIT DIESEL LF9620(2), FF5369W	<b>MK12526</b>	mitsubishi AF25447, FF5221, LF3336	<b>MK12624</b>	ISUZU LF3854, LF551A, FF5108
<b>MK12499</b>	DETROIT DIESEL LF3620(2), FS19536	<b>MK12527</b>	mitsubishi FF5224, LF3336	<b>MK12638</b>	CATERPILLAR LF3566(3), FF5132(2), HF7473(2), HF7779
<b>MK12500</b>	TOYOTA AF4509, FF5030, FF5385, LF3399	<b>MK12528</b>	TOYOTA AF4509, FF5030, LF3399	<b>MK12639</b>	DETROIT DIESEL LF3380(2), FF5036, FF5037
<b>MK12501</b>	TOYOTA AF4509, FF5159, LF3608	<b>MK12529</b>	TOYOTA AF4956, FF5177, LF3874	<b>MK12641</b>	NEW HOLLAND LF3630, FF5418
<b>MK12503</b>	HOLDEN AF4616, FF5030, LF3508	<b>MK12546</b>	CATERPILLAR LF777, LF691A, FF5264, 255622S	<b>MK12672</b>	THERMO-KING LF3746, FS19580
<b>MK12504</b>	HOLDEN AF4616, FF5030, LF3528	<b>MK12547</b>	CUMMINS LF9009, FS1000	<b>MK12673</b>	CATERPILLAR LF691A, FF5319, FF105
<b>MK12505</b>	HOLDEN FF5180, LF3462	<b>MK12552</b>	TOYOTA AF4509, LF3608, FF5159, HF6173, FF5385	<b>MK12674</b>	CUMMINS LF3959, FS1280, FF5052
		<b>MK12557</b>	CUMMINS LF9000, FS1000	<b>MK12678</b>	CUMMINS LF3959, FS1251
















## E. PRODUCT GUIDE

<b>MK12683</b>	CATERPILLAR LF691A, FS1029W, FF5319	<b>MK12764</b>	CATERPILLAR LF3566, LF777, FS1029W	<b>MK12845</b>	FORD LF3681, FF5033
<b>MK12684</b>	CUMMINS LF9001, FS1007	<b>MK12770</b>	MACK LF9667(2), CS41005, WF2015	<b>MK12850</b>	CATERPILLAR LF691A, FF105, FF185
<b>MK12685</b>	CATERPILLAR LF691A, FS1212, FF5264	<b>MK12775</b>	VOLVO LF3675(2), LF3654, FF5369W	<b>MK12852</b>	CATERPILLAR FF5319, FF5369W, LF691A
<b>MK12687</b>	THERMO-KING LF3746, FS19580, AH1189	<b>MK12777</b>	CUMMINS LF9001, FS1000, WF2051	<b>MK12889</b>	VOLVO LF3321(2), LF3654, FF5507
<b>MK12688</b>	CATERPILLAR LF691A, FF5319, FS1212	<b>MK12778</b>	CUMMINS LF9001, HF7608, FS1000, WF2051	<b>MK12897</b>	MACK LF667(2), CS41005, FF5369W
<b>MK12690</b>	GMC LF3679, FF5033	<b>MK12779</b>	CATERPILLAR LF667, FF185(2)	<b>MK12902</b>	CUMMINS LF9001, FS1029W
<b>MK12691</b>	SCANIA LF3730, 3931308S	<b>MK12782</b>	CUMMINS LF3000, FS1029W, FS1000, WF2071	<b>MK12906</b>	VOLVO LF3675(2), LF3654, FF5507, FF5369W
<b>MK12693</b>	CATERPILLAR LF691A, LF777, FF5319, FF105	<b>MK12790</b>	MACK LF667(2), FF5381, FF5382, CS41005, WF2015	<b>MK12907</b>	MACK CS41005, LF16101, FF5369W
<b>MK12694</b>	CUMMINS LF9001, FS1029W, WF2071	<b>MK12796</b>	MACK LF667(2), FS19558, CS41005	<b>MK12909</b>	CUMMINS LF16046, FF5405
<b>MK12695</b>	CATERPILLAR LF691A, FF5319, FF5207, WF2071	<b>MK12803</b>	CATERPILLAR LF9691, FF5319, FS1029W	<b>MK12910</b>	MERCEDES-BENZ LF9001, FF5369W, FF2200, WF2126
<b>MK12696</b>	CATERPILLAR LF691A, FF5319, WF2071	<b>MK12812</b>	CUMMINS LF9001, WF2072, FF5369W, CC2602B	<b>MK12917</b>	CUMMINS WF2051, FS1000, LF9009
<b>MK12697</b>	CATERPILLAR LF691A, FF5319, FS1000	<b>MK12814</b>	DETROIT DIESEL LF9620(2), FS19513, FF5206, WF2071	<b>MK12918</b>	DETROIT DIESEL WF2051, FF5369W, LF3620(2)
<b>MK12698</b>	MACK LF667(2), CS41005, FF5381, FF5382	<b>MK12815</b>	CATERPILLAR LF9691A, FF5207, FF5319, WF2071	<b>MK12932</b>	VOLVO LF3675(2), FF5507, LF3654
<b>MK12700</b>	CATERPILLAR LF667, FF5320	<b>MK12818</b>	CATERPILLAR LF691A, LF777, FF211, FS19532	<b>MK12933</b>	CUMMINS FS1003, LF9009, WF2071, FF5488
<b>MK12746</b>	CUMMINS LF9001, FS1000	<b>MK12817</b>	INTERNATIONAL HARVESTER LF3883, FF203, FF5269	<b>MK12941</b>	INTERNATIONAL TRUCKS LF9620(2), FS19624
<b>MK12747</b>	CUMMINS LF9001, FS1040	<b>MK12818</b>	NAVISTAR LF3630, FS1298, HF6056	<b>MK12942</b>	CUMMINS LF9009, FS19624, WF2071
<b>MK12749</b>	GMC LF3679, LF3342, FF5033	<b>MK12820</b>	PERKINS LF3615, AH19001, FF5260	<b>MK12945</b>	CATERPILLAR LF691A, FS19624, FF5319
<b>MK12750</b>	CUMMINS LF9001, FS19557, CC2602B	<b>MK12821</b>	CUMMINS FF2200, LF9001, WF2126	<b>MK12946</b>	CATERPILLAR FF202, FF5319, LF691A
<b>MK12756</b>	CUMMINS LF3342, LF3349, FF149, FS1251, HF6056	<b>MK12822</b>	GMC LF796, FF5033	<b>MK12950</b>	DETROIT DIESEL LF3620(2), FS19624, CC2602B
<b>MK12758</b>	CARRIER LF787, LF778, FF5458	<b>MK12824</b>	CUMMINS LF9001, FS1212	<b>MK12952</b>	MACK LF16101(2), FF5382, FF5381, CS41005
<b>MK12759</b>	CUMMINS LF9009, FS1022, WF2071	<b>MK12828</b>	CATERPILLAR LF667, FS1251, FF5321	<b>MK12953</b>	MACK LF667, FF234, HF6243, 3838230S, FF5320, WF2015
<b>MK12760</b>	VOLVO LF9667(2), LF3654, FF5272	<b>MK12831</b>	CUMMINS LF9001, WF2127, FS19559	<b>MK12955</b>	CATERPILLAR LF691A, FS1001, FF5320
<b>MK12763</b>	MACK LF667(2), FF172, FF222, WF2015				

## E. PRODUCT GUIDE

<b>MK12956</b>	MACK LF667(2), FF172, FF222, CS41000, HF6557, WF2015	<b>MK13024</b>	MACK FF172, FF222, LF16101(2), WF2015, CS41000	<b>MK13048</b>	VOLVO LF667(2), LF777, FF42000(2)
<b>MK12959</b>	MACK LF667(2), CS41010, FF5381, FF5382	<b>MK13025</b>	MACK FF172, FF171, LF16101(2), WF2015	<b>MK13049</b>	CATERPILLAR LF9691A, FF5319, FF202
<b>MK12961</b>	CUMMINS FS19579E, HF6056(2), LF3970	<b>MK13026</b>	MACK FF172, FF171, LF16101(2), WF2015, CS41000	<b>MK13050</b>	DETROIT DIESEL LF3671(2), FS19624
<b>MK12963</b>	CUMMINS FS1003, 3930618S	<b>MK13027</b>	MACK FF172, FF222, LF16101(3), WF2022	<b>MK13051</b>	MERCEDES-BENZ FF5405, LF16046, FS1029W
<b>MK12992</b>	CUMMINS LF9001, FF2200, FS19729	<b>MK13028</b>	MACK FF172, FF222, LF16101(2), WF2022, CS41000	<b>MK13052</b>	VOLVO LF3675(2), LF3651, FS19728
<b>MK12993</b>	CUMMINS LF9001, FF2200, FF2203, WF2126	<b>MK13030</b>	IHC LF3883, FF5019	<b>MK13053</b>	MACK LF3379(2), CS41005, FS19728
<b>MK12995</b>	MACK LF3973(2), CS41011	<b>MK13031</b>	CUMMINS LF3349, FF5052, FF5059, LF3342, HF6057	<b>MK13054</b>	CUMMINS LF9001, FS1003, FS19727
<b>MK13006</b>	CATERPILLAR LF777, LF3566, FF211	<b>MK13032</b>	CUMMINS LF9009, FF5052, FF5079, FS1280, WF2071	<b>MK13057</b>	CUMMINS LF3914, FF5380, FS19513
<b>MK13007</b>	CUMMINS FF2200, FF2203, LF9001	<b>MK13033</b>	VOLVO LF3654, LF3675(2), WF2108, FF5507	<b>MK13058</b>	CUMMINS LF9001, FF2200, FF5369W
<b>MK13008</b>	CATERPILLAR LF777, LF3566, FF202, FF5319	<b>MK13034</b>	VOLVO LF3654, LF3675(2), WF2108, FF5507	<b>MK13061</b>	CATERPILLAR LF3566, FS19729, FF5319
<b>MK13009</b>	CATERPILLAR LF691A, FS19683, FF5319	<b>MK13036</b>	VOLVO LF3675(2), LF3654, FS19532, FF5507, WF2129	<b>MK13062</b>	IHC LF16166, FF5418, HF35296
<b>MK13010</b>	CUMMINS LF9001, FF2200, FS19729, WF2127	<b>MK13037</b>	CATERPILLAR LF3566, FF5319	<b>MK13063</b>	IHC LF3883, FF5269, HF35296
<b>MK13012</b>	FORD LF3681, FF5455	<b>MK13038</b>	CUMMINS LF9001, FS19729, WF2126, FF2200	<b>MK13064</b>	MACK LF667(2), CS41000, FS1219, FF222, WF2015
<b>MK13013</b>	DEUTZ AG AF418, LF3311, FS20102, FF5040, HF6185, AF490M	<b>MK13039</b>	CUMMINS LF9001, FS19729, WF2126	<b>MK13065</b>	MACK LF3973(2), CS41005, FS1029W, WF2015
<b>MK13014</b>	CUMMINS LF3970, FS19596	<b>MK13040</b>	CUMMINS LF9001, FS19729	<b>MK13066</b>	CATERPILLAR LF3566, FF5319, FS19807
<b>MK13015</b>	DETROIT DIESEL LF3620(2), FS19624	<b>MK13041</b>	CUMMINS LF3959, FS1251, HF6057, LF3342	<b>MK13067</b>	MERCEDES-BENZ LF3914, FF5380, CS41008, FS19624
<b>MK13016</b>	CUMMINS FF5369W, LF9001	<b>MK13042</b>	CATERPILLAR FF202, FF5319, LF691A	<b>MK13068</b>	CUMMINS LF3654, LF3675(2), FF5507, FS19551
<b>MK13017</b>	CUMMINS LF3806, FS19616	<b>MK13043</b>	MERCEDES-BENZ FS19624, LF3671(2), WF2051	<b>MK13069</b>	CUMMINS LF691A, FF211, FF202
<b>MK13019</b>	CATERPILLAR LF3379, HF6553, FF5321, FF5322, FS19555	<b>MK13044</b>	CATERPILLAR LF3566, CC2525, FF5319, FS1029W	<b>MK13070</b>	CUMMINS LF9001, FF5488, FS1003
<b>MK13020</b>	CUMMINS LF9025, FS19684E, CS41013	<b>MK13045</b>	CUMMINS LF9025, FS19684E	<b>MK13071</b>	VOLVO LF3675(2), LF3654, FS1029W, FF5507
<b>MK13021</b>	MACK LF3328(2), FF172, FF222, CS41000, HF6557, WF2015	<b>MK13046</b>	CUMMINS LF3854, FF5617	<b>MK13082</b>	CUMMINS LF9009, FS1003, FF5488
<b>MK13022</b>	MERCEDES-BENZ LF3914, FF5380, FS19624	<b>MK13047</b>	CUMMINS LF3671, FF5206, FS19513	<b>MK13083</b>	PERKINS FF5260, LF3615
				<b>MK13084</b>	CUMMINS LF9001, FS19624

## E. PRODUCT GUIDE

MK13085	CUMMINS LF3000, FF5488, FS1003	MK13112	DETROIT DIESEL LF9620(2), FS1029W	RN24005	DAVCO 570720 Continuous Oil Change Module- 24 Volt DC- Quarts
MK13086	CUMMINS LF3854, FF5160, LF551A	MK13113	VOLVO LF3675(2), LF3654, FF5507, FF5369W, WF2108		
MK13087	CUMMINS LF9009(2), FS1000(2), WF2076, CC2543, 3318168S, CC2602B	MK13118	CUMMINS LF3914, FF5380	RN24006	DAVCO 571002 Oil Level Regulator. Includes mounting bracket, hose and fittings.
MK13090	CATERPILLAR LF3566, FF5319, CC2525	MK13121	CUMMINS LF3536, LF778, FF5301		
MK13091	CUMMINS LF667, FS1000, FF5321	<b>Fuel Filters</b>		RN24007	DAVCO 570102 Oil Level Regulator. Does not include mounting bracket, hose and fittings.
MK13092	CATERPILLAR LF691A, FF5319, FS20201, WF2077	NG5900	CUMMINS 3606712 Filter used with 3893692S L10G, B&C Natural Gas Version of 10 liter engine		
MK13093	CUMMINS LF3914, FS19521, FF5380		Overall Height: 7.35 (187) Largest OD: 3.78 (96) Thread Size: 1 1/2-16 UN-2B	RN24008	DAVCO 570203 Replaces RN24020 Analog Slow Flow Meter with counter (gallon)
MK13094	CUMMINS LF787, FF5380	RN24000	DAVCO 570715 Continuous Oil Change Module- 12V DC- Gallons		
MK13095	CUMMINS LF3973(2), FS19558			RN24009	DAVCO 570233 Counter Assembly, MRA
MK13096	CUMMINS LF3566, FF5319, FS1000	RN24001	DAVCO 570716 Continuous Oil Change Module- 24V DC- Gallons		
MK13097	CATERPILLAR LF691A, FF202, FF5264			RN24010	DAVCO 570205 Analog Slow Flow Meter with counter (liter)
MK13098	CUMMINS LF9001, FS19799, FF2200, WF2126	RN24002	DAVCO 570717 Continuous Oil Change Module- 12 Volt DC- Liters		
MK13099	CUMMINS LF9001, FS1000, WF2123			RN24011	REN 111 Liquid Level Switch (U.L.)
MK13100	CUMMINS LF3671(2), FS19727	RN24003	DAVCO 570718 Continuous Oil Change Module- 24 Volt DC- Liters		
MK13103	CUMMINS LF695, LF702, FF204, FF185, AH1189			RN24012	DAVCO 571009 5 Gallon (18.9 liter) Oil Supply Reservoir and Pedestal Stand with Calibrated Sight Gauge & Shutoff Valve
MK13104	CATERPILLAR LF667, FF5320, FF234, HF6243, HF35197(3), WF2051, 3838230S	RN24004	DAVCO 570719 Continuous Oil Change Module- 12 Volt DC- Quarts		
MK13106	CUMMINS LF9009, FS1029W			RN24014	DAVCO 570409 Tank with Sight Gauge & Shutoff Valve- REN Product
MK13107	CUMMINS LF9009, FS1029W, WF2071				
MK13108	CUMMINS LF9009, FS1029W, WF2051				
MK13109	CATERPILLAR LF9691A, FF5207, FF5319				
MK13110	CATERPILLAR LF9691A, FF5319, FS1029W				
MK13111	DETROIT DIESEL LF9620(2), FF5206, FF5207, WF2051				