

# New Product Bulletin

Europe, Russia/CIS & Middle East Parts

September 2020

Part Number                      Application                      Cross-ref.                      Dimensions                      Description                      Segment



**FF5896**

Hyundai Excavators  
R140LC-7A, R140LCD-7A, R140W-7A, R160LC-7A,  
R160LCD-7A, R170W-7A, R180LC-7A, R180LCD-7A  
equipped with Mitsubishi Engine D04FD-TAA

Hyundai  
XJAF-02430 & XJAF-03012;  
Mitsubishi 32562-60200,  
32R62-00100, 34362-04100;  
Sakura FC-18052

H: 175 mm  
OD: 97,5 mm  
Thread: 1.0-14.0 UN-2B

Fuel Filter, Spin On  
Media Type: Cellulose  
Gasket ID: 57,5 mm  
Gasket OD: 68 mm



**HF29161**

Manitou Forklifts MLT840-137 PowerShift;  
MT1436R & MT1840R equipped with Perkins engine;  
MLT840-115 PowerShift ST3B;  
New Holland Telescopic Handlers  
LM5040, LM5060 & LM5080

Manitou 745878;  
New Holland 84237745;  
Sakura HC-51030








H: 153,5 mm  
OD: 97 mm  
Thread: M1 3/8X12.0-2B


Hydraulic Filter, Spin On  
Media Type : Microglass  
Stand Pipe: No  
Gasket OD: 70 mm



Parts from other regions\* =>

Made to order products (lead time 6-8 weeks) and currently not available/ not in inventory in Europe.  
Subject to minimum order quantities (MOQ's) – pls. validate details with your Area Sales Manager.

<b>AF4341</b>	New Holland Tractors T4 & T5-Series & Steyr Tractors Kompakt-Series	New Holland 84479225, Donaldson P952780, M+H CF10006, Wix WA10552,	L 254 mm ID: 74 mm OD: 92,2 mm	Air Filter, cylindrical Secondary Air Filter for AF4340 Media Type: Cellulose	
<b>AF56082</b>	Hitachi Excavators EX & ZX-Series	Hitachi 4441139 & 4S00684; Bald- win PA5662; Sakura CA-27050, Napa 550268, Wix WP10268	H: 168,5 mm L: 287,5 mm W: 5 mm	Cabin Air Filter	
<b>AF56083</b>	Komatsu Excavators PC400-8, PC400-8R, PC400LC-8(R), PC450LC-7, PC600-8, PC600LC-8, PC800-8, PC800-8EO, PC800-8K, PC800LC-8, PC800LC-8EO & PC800LC-8K	Komatsu 208-979-7740; Sakura CA-56080; Baldwin PA30152, Carquest 93726	H: 101,5 mm L: 199 mm W: 19,5 mm	Cabin Air Filter	
<b>FF42103</b>	Yanmar engines LA-Series applications (L40, L48, L60, L70, L75, L90 & L100)	Yanmar 114250-55120, 114250-55121	H: 130,5 mm ID: 8 mm OD: 39,7 mm	Fuel Filter, Cartridge Media Type: Cellulose	
<b>FF42104</b>	Komatsu Excavators PC20R-8 & PC27R-8; PC20MR-3; PC30MRX-1; Komatsu Loader SK815-5	Komatsu 3EB-05-41290, Yanmar 129052-55630, New Holland YJ21P01008P2, Baldwin BF9906, Wix WF10512, Napa 600512	L: 81,8 mm OD: 65,1 mm	Fuel Filter, In Line	
<b>FF42106</b>	Kubota Tractors B2410HSD, B2410HSE, B2710HSD, B2910HSD, B3030HSD; Kubota Utility Vehicles RTV900-Series	Kubota 6A32059930, Baldwin PF9911, Wix 33830, Carquest 86830, Napa 3830	H: 54 mm ID: 6 mm OD: 46 mm	Fuel Filter, Cartridge Media Type: Cellulose	
<b>FF42110</b>	Kubota Tractors M6060 & M7060;	Kubota 1J800-43170, Sakura FC-10121, Wix WF10383, Napa 600383	H: 100 mm OD: 90 mm Thread: M20.OX1 1/2-6H	Fuel Filter, Spin On Media Type: Cellulose Gasket ID: 51,2 mm Gasket OD: 64,4 mm	

<b>LF16424</b>	RAM Light Trucks Promaster 1500, 2500 & 3500 equipped with Chrysler V6 3.6L	Chrysler 68191349AA, 68191349AB, Baldwin P9600, Sakura EO-66020, Fram CH11665, Wix WL10010, Napa 100010, Luberfiner P1009	H 157 mm ID: 24 mm OD: 50,5 mm	Lube Filter, cartridge Media Type: Cellulose Gasket ID: 24 mm Flow Direction: Outside In	
<b>LF16445</b>	Hino Trucks 500-Series & Ranger FC & FD-Series	Hino 15607-2200, Sakura C-1319, Donaldson P506094, Napa 400270	H: 156,7 mm OD: 122 mm Thread: M1 1/2X16.0-2B	Lube Filter, Spin On Media Type: Cellulose Gasket ID: 98 mm Gasket OD: 114 mm Flow Direction: Outside In	
<b>HF29151</b>	Hitachi Excavators EX1800 & EX1900-Series; EX2500 & EX5500-Serie	Hitachi 4253230 & 4688140, Baldwin PT23560, Carquest 95072	H: 162,5 mm ID: 38 mm OD: 84 mm	Hydraulic Filter, Cartridge Media Type: Wiremesh Gasket OD: 82 mm Flow Direction: Outside In	
<b>HF29156</b>	Kubota Tractors L3410HST & L3710HST; Kubota Backhoe Loader M59	Kubota TA240-59900, TA240-59901 & HHTA0-59900, Baldwin BT9358, Carquest 84616, Wix 57616	H: 147 mm OD: 95,7 mm Thread: 1 1/8-16.0 UN-2B	Hydraulic Filter, Spin On Media Type: Microglass Gasket OD: 75,3 mm Stand Pipe: No	
<b>HF29162</b>	Komatsu Loaders WA200PT-5, WA250-5, WA250PT-5, WA320-5, WA320PT-5, WA320PZ-6	Komatsu 418-18-34160, Donaldson P502622, Baldwin BT23604, Sakura HC-56060, Wix WL10042, Carquest 95107, Napa 400042	H: 154 mm OD: 87 mm Thread: M45.0X1 1/2-6H	Hydraulic Filter, Spin On Media Type: Microglass Gasket OD: 60,3 mm Stand Pipe: No	
<b>HF29163</b>	Hitachi Loaders LX & ZW-Series	TCM 26557-82051; Hitachi 26557-82051	H: 261 mm OD: 110,2 mm Thread: M60.0X2.0-6H	Hydraulic Filter, Spin On Media Type: Microglass Gasket OD: 85,3 mm Stand Pipe: No	
<b>HF29164</b>	Komatsu Graders GD555-Serie; Komatsu Loaders WA100, WA150, WA320, WA200 & WA250-Series	Komatsu 419-60-35152, Baldwin BT9360, Wix WL10293, Napa 400293	H: 283 mm OD: 129,3 mm Thread: M120.0X2.0-6H	Hydraulic Filter, Spin On Media Type: Cellulose Gasket OD: 110 mm Stand Pipe : No	
<b>HF29165</b>	Kobelco Excavators ED, SK, SR-3, SR-Series; New Holland Construction E,EC, LE-Series	Kobelco YN52V01020P1 & YN-52V01021P1, YV52V01003R110, YN52V01010P1, Donaldson P502446, Baldwin PT9476-MPG, M+H HD15003, Carquest 94149	H: 130,5 mm ID: 96,7 mm OD: 145 mm	Hydraulic Filter, Cartridge Media Type: Microglass Flow Direction: Outside In	

# Replaced and obsoleted parts

Part number	Replacement PN	Part number	Replacement PN
AF444	no replacement	HF7757	no replacement
AF25232	no replacement	HF7764	no replacement
AF27695	AF27994	HF7770	no replacement
AF27696	AF27993NF	HF7773	no replacement
AS2322	no replacement	HF7774	no replacement
CV50115	CV50117	HF7791	no replacement
FF219	no replacement	HF7792	no replacement
FF244	no replacement	HF7793	no replacement
FF5148	no replacement	HF7804	no replacement
FF5181	no replacement	HF7810	no replacement
FH23624M	FH23621M	HF30209	no replacement
FS42260	FS1022	HF30889	no replacement
HF7701	no replacement	LF3583	LF3481
HF7710	no replacement	LK49001	no replacement
HF7727	no replacement	256546S	256172S
HF7732	no replacement	3316633S	no replacement
HF7740	no replacement	3950445S	3944449S
HF7747	no replacement	3964354S	OS806